Sterling 360, A/C System Receiver-Drier Replacement Guidelines—Group 55

83-14

L-Line A-Line Cargo Acterra Condor > 360

Sterling Service Bulletin

Receiver-Drier Replacement Guidelines

Sterling does not recommend periodic maintenance of the receiver-drier.

NOTE: The following guidelines do not replace normal maintenance of the HVAC system which may vary by application and customer discretion.

The receiver-drier must be replaced if one of the following occurred:

- The refrigerant system experienced catastrophic failure that put debris into the system—this debris may
 have been from an internal failed part within the A/C compressor, or from a breakdown of the desiccant
 within the receiver-drier.
- The refrigerant system was empty due to a system leak when the vehicle arrived for service, confirmed by zero pressure at the A/C system service ports.

The two conditions above are the only circumstances in which the receiver-drier is covered if normal warranty applies. Under all other circumstances, the receiver-drier is considered a consumable item and as such cannot be claimed.